

S-7 工具セット

このたびはホーザン S-7 工具セット をお買い上げいただきまことにありがとうございます。
この製品情報をご確認のうえ、正しくお使いください。



D-29-100	調整ドライバー	P-15-150	ラジオペンチ
D-540-100	プラスドライバー No. 0	P-43-150	ペンチ
D-555-100	プラスドライバー No. 2	P-87	ピンセット
D-630-100	マイナスドライバー 2.5mm	W-230-150	モンキーレンチ
D-640-100	マイナスドライバー 4.0mm	Z-341	コンベックスルーラー
D-840-5.5	ナットドライバー 5.5mm	SB-1	ハンダ
H-869	耐食ビット付ハンダゴテ		カッターナイフ
K-172	ヤスリ 平		ビニールテープ
N-4-125	斜ニッパー		

■ ツールケース 付

ご使用上の注意

間違った使い方をすると思わぬ事故につながります。
各工具の使用目的を守ってください。

⚠警告

1. 工具類のハンドルは絶縁ではありません。電気が流れている個所には使用しないでください。感電するおそれがあります。
2. 切断用やストリップ用の工具をご使用の際は保護メガネを着用してください。切断片が目に入ると大変危険です。

⚠注意

1. サイズに適合性のある工具はサイズを確認してご使用ください。
2. 工具に割れ、欠け、摩耗、変形が認められるときは使用しないでください。
3. 工具を改造しないでください。

H-869 耐食ビット付ハンダゴテの取り扱いについて次の点にご注意ください。

⚠警告

1. 通電中はハンドル以外を触らないでください。ヤケドのおそれがあります。
2. 燃えやすいもの、可燃物の近くでは使用しないでください。火災の原因となります。
3. 使用時にはコテ台を併用してください。火災ややけどの原因となります。
4. 規定以上の電圧を与えないでください。火災の原因となります。
5. 電源コードに傷や破損が認められるときは使用しないでください。火災や感電のおそれがあります。

⚠注意

1. 新品時の初通電では煙が出ますが故障ではありません。煙は5、6分で収まり、以後は発煙しません。
2. ハンダゴテのコテ先は鉛フリーハンダで覆っており、少し長く空焼きをすると焼き付きをおこします。初めて通電されるときは、新しいハンダを盛ってから使用してください。収納の際は、一度ハンダをふきとってから新しいハンダで先端を覆い、電源を切ってください。先端以外は、特殊鉄メッキにアルミ皮膜です。絶対にヤスリがけしないでください。

ホーサン株式会社

本社 〒556-0021 大阪市浪速区幸町1-2-12

製品・補修部品はWebサイトにてご購入いただけます。

<https://www.hozan.co.jp/>



技術的なお問い合わせ

ホーサン テクニカルホットライン

☎06-6567-3132 / E-mail : th@hozan.co.jp

【月曜日から金曜日(祝日を除く)の10:30~12:00、13:00~17:00】

S-7 TOOL KIT

Thank you for purchasing the HOZAN S-7 TOOL KIT. Please check the contents and use following the instructions.



D-29-100	Alignment tool	P-15-150	Long nose pliers with side cutter
D-540-100	Phillips screwdriver No.0	P-43-150	Pliers with side cutter
D-555-100	Phillips screwdriver No.2	P-87	Tweezers
D-630-100	Slotted screwdriver 2.5mm	W-230-150	Adjustable wrench
D-640-100	Slotted screwdriver 4.0mm	Z-341	Measure tape
D-840-5.5	Nut driver 5.5mm	SB-1	Solder
H-869	Soldering iron w/rust-proof tip		Utility knife
K-172	File, flat		Electrical tape
N-4-125	Diagonal cutter		

■ With tool case

Precautions

Incorrect handling could cause an unexpected situation. Follow the purpose of each tool.

Warning

1. Handles of tools are not insulated. Do not use on energized places. This could cause a shock.
2. Wear goggles to protect your eyes against flying debris when using cutting tools or wire stripping tools. Core wire or insulation fragments could injure your eyes.

Caution

1. Use the proper tool size for each application.
2. Do not use tools which are cracked, broken, worn, or deformed, etc.
3. Do not remodel the tools.

When handling THE H-869, SOLDERING IRON, note the following instructions.

Warning

1. Do not touch an area other than the handle while power is on. This could cause a burn.
2. Do not use the soldering iron near flammable or combustible materials. This could cause a fire.
3. Use a soldering iron stand to avoid causing a fire or burn.
4. Do not supply greater than rated voltage. This could cause a fire.
5. Do not use if a cut or damage is found on power cord. This could cause a fire or a shock.

Caution

1. It is normal for a new soldering iron to smoke during first use, but smoke will soon stop.
2. The tip of the soldering iron is covered with lead-free solder which is easily burned and stuck if heated without using even for a short time.
Tin with solder when energize for the first time.
Turn off the power after wipe the used solder and tin with new solder.
Do not file this tip since the area other than the point is covered with iron and aluminum plate.

HOZAN CO., LTD.

1-2-12 Saiwaicho, Naniwa-ku, Osaka 556-0021, Japan
<https://www.hozan.co.jp/E/> E-mail: th@hozan.co.jp